

5666

*ALERT*ALERT*ALERT*

Facilities Management Outage Notification

Please Post Centrally in Your Department

HVAC Outage

BLDG: 0068 CLARK HALL

Affected Floors / Rooms: Outage will impact lab exhaust on ground, 1st, and 2nd floors and general exhaust in the entire Clark addition. It will not impact heating or cooling, and it will not impact the original portion of Clark at all

Impact to Building Occupants: No General Exhaust Clean and remove duct and replace with new stainless steel duct and valve

Scheduled Start Date and Time:	2020-May-27 07:00
Scheduled End Date and Time:	2020-May-27 15:00
Reason for Outage:	Replace duct from fume hood in Room G086 to main duct in hall.
Requested By:	Bret Gentry (UVA FM Project Services)
Outage Coordinator	Ryan Taylor 434-981-8874
Customers with Whom the Outage was Coordinated:	Cindy Allen
Outage Approved By:	Ryan Taylor (UVA FM Operations)

Important Notes:

- 1. The specified utility or building system will be out of service as noted above. Please advise the Outage Coordinator immediately if this can not be accommodated in areas under your control or direction
- Those performing work associated with this outage <u>MUST</u> notify the Systems Control Center (982-4685) PRIOR TO THE START and upon COMPLETION of all work

*ALERT*ALERT*ALERT*

Please use the below link to unsubscribe from these notification, change, or subscribe to other building lists

https://www.fm.virginia.edu/resources/outagesubs.html