

9683

*ALERT*ALERT*ALERT*

Facilities Management Outage Notification

Please Post Centrally in Your Department

HVAC Outage REVISED - SEE NEW DATES BELOW

BLDG: 0068 CLARK HALL

Affected Floors / Rooms: Ground Floor Rooms G083A and G077

Impact to Building Occupants: No Chemical Exhaust
The exhaust fan will be shut down to remove duct in the chase, then restored once it has been capped. This will only impact Rooms G083A and G077

| Scheduled Start Date and Time: | 2021-Apr-14 07:00 | | | |
|--|--|--|--|--|
| Scheduled End Date and Time: | 2021-Apr-14 16:00 | | | |
| Reason for Outage: | Remove existing duct, add fume hood and install new duct. | | | |
| Requested By: | Bret Gentry (UVA FM Project Services) | | | |
| Outage Coordinator | Ryan Taylor 434-981-8874 | | | |
| POC for Group Performing Work: | ColonialWebb Jonathan Bell 540-416-3782 Colonial Webb AC Dove 540-717-2331 | | | |
| | FM Responsible Person: Bret Gentry 434-531-8211 | | | |
| Customers with Whom the Outage was Coordinated: | Wynne Stuart, Elizabeth Jackson, Guy Mengel | | | |
| Outage Approved By: | Ryan Taylor (UVA FM Operations) | | | |

Important Notes:

- 1. The specified utility or building system will be out of service as noted above. Please advise the Outage Coordinator immediately if this can not be accommodated in areas under your control or direction
- 2. Those performing work associated with this outage <u>MUST</u> notify the Systems Control Center (982-4685) PRIOR TO THE START and upon COMPLETION of all work

*ALERT*ALERT*ALERT*