

24489

## \*ALERT\*ALERT\*ALERT\*

**Facilities Management Outage Notification** 

Please Post Centrally in Your Department

## Fire System Smoke Detection, Fire System Panel Outage

**BLDG: 0406 Fayerweather Hall** 

Affected Floors / Rooms: Room M115 (mechanical)

Impact to Building Occupants: No Fire Alarms
Please email our team to confirm the outage at:
Randy Spencer – DRS2Y@virginia.edu
Jacob Campbell – JRC3ZZ@virginia.edu

Scheduled Start Date and Time:	2025-Jul-30 05:00
Scheduled End Date and Time:	2025-Jul-30 08:00
Reason for Outage:	Welding needs to take place during this outage and this will be to disable any smoke/heat detectors along with any HVAC duct detectors.
Requested By:	David Hermes (UVA FM Operations)
Outage Coordinator	Donald (Randy) Spencer 434-531-6993
Customers with Whom the Outage was Coordinated:	Emily Chen
Outage Approved By:	Randy Spencer (UVA FM Operations)

## **Important Notes:**

- 1. The specified utility or building system will be out of service as noted above. Please advise the Outage Coordinator immediately if this can not be accommodated in areas under your control or direction
- 2. Those performing work associated with this outage <u>MUST</u> notify the Systems Control Center (982-4685) PRIOR TO THE START and upon COMPLETION of all work

## \*ALERT\*ALERT\*ALERT\*