

ALERT*ALERT*ALERT*ALERT

Facilities Management Outage Notification

Please Post Centrally in Your Department

Building Steam MTHW Outage

AFFECTED BLDGS:

0406 Fayerweather Hall

0407 Bayly Building

Impact to Building Occupants: Building will be cooler and more humid, No heating

Tied to outage to remove heat exchanger and heating will not be needed during the course of the outage. Outgae set to occur early in the morning to keep impact to a minimum.

Please email our team to confirm the outage at:

Randy Spencer – DRS2Y@virginia.edu

Jacob Campbell – JRC3ZZ@virginia.edu

Scheduled Start Date and Time:	2025-Jul-30 05:00
Scheduled End Date and Time:	2025-Jul-30 08:00
Reason for Outage:	To cut/cap and remove associated MTHW piping.
Requested By:	David Hermes (UVA FM Operations)
Outage Coordinator:	Donald (Randy) Spencer 434-531-6993 drs2y@virginia.edu
Point of Contact for Performing Work:	David Hermes 434-989-2352
Outage Approved By:	Randy Spencer (UVA FM Operations)

Important Notes:

1. The specified utility or building system will be out of service as noted above. Please advise the Outage Coordinator immediately if this can not be accommodated in areas under your control or direction
2. Those performing work associated with this outage **MUST** notify the Systems Control Center (982-4685) PRIOR TO THE START and upon COMPLETION of all work

ALERT*ALERT*ALERT*ALERT

Please use the below link to unsubscribe from these notification, change, or subscribe to other building lists

<https://www.fm.virginia.edu/resources/outages/outagesubs.html>