

19974

## \*ALERT\*ALERT\*ALERT\*

**Facilities Management Outage Notification** 

Please Post Centrally in Your Department

Fire System Smoke Detection Outage EXTENDED UNTIL 2024-Jul-16 12:00

**BLDG: 0057 Robertson Hall** 

ALL FLOORS AFFECTED

Impact to Building Occupants: None
Please Confirm you have received notification of this outage by emailing our
Team at:

Randy Spencer: DRS2Y@virginia.edu Jacob Campbell: JRC3ZZ@virginia.edu

Scheduled Start Date and Time:	2024-Jul-15 07:00
Scheduled End Date and Time:	2024-Jul-15 16:00
Reason for Outage:	The elevator contractor needs to do some welding in the south elevator shaft in the basement mechanical room (where DPR is working). We are requesting to disable nearby smoke detectors from 7am - 4pm for one day so they can perform work without setting off alarms and sending fire trucks to the building.
Requested By:	Charlotte Dickerson (UVA FM FP&C)
Outage Coordinator	Donald (Randy) Spencer 434-531-6993
POC for Group Performing Work:	DPR Construction John Aulbach 540-529-9795  FM Responsible Person: Charlotte Dickerson 434-906-9401
Customers with Whom the Outage was Coordinated:	Bryan Lewis
Outage Approved By:	Randy Spencer (UVA FM Operations)

## **Important Notes:**

<sup>1.</sup> The specified utility or building system will be out of service as noted above. Please advise the Outage Coordinator immediately if this can not be accommodated in areas under your control or direction

<sup>2.</sup> Those performing work associated with this outage <u>MUST</u> notify the Systems Control Center (982-4685) PRIOR TO THE START and upon COMPLETION of all work

## \*ALERT\*ALERT\*ALERT\*

Please use the below link to unsubscribe from these notification, change, or subscribe to other building lists

https://www.fm.virginia.edu/resources/outages/outagesubs.html