16610

*ALERT*ALERT*ALERT*

Facilities Management Outage Notification

Please Post Centrally in Your Department

Fire System Smoke Detection, Fire System Panel Outage

Fire System Chimes and Strobes WILL NOT be activated during testing

BLDG: 0058 Rouss Hall

ALL FLOORS AFFECTED

Impact to Building Occupants: No Elevators, No Fire Alarms
Updated Outage Notes: Work will affect Rouss and Robertson Hall.
Contractor may need to access office space to change out smoke detectors during this project. Fire crew may need additional testing during working days. Elevators will be affected on different days. An additional outage will be sent to communicate additional details.

Please Confirm you have received notification of this outage by emailing our Team at:

Randy Spencer: DRS2Y@virginia.edu Jacob Campbell: JRC3ZZ@virginia.edu

This Outage Will Occur Daily: 06:00-18:00

Scheduled Start Date and Time:	2023-Oct-27 06:00
Scheduled End Date and Time:	2023-Nov-02 18:00
Reason for Outage:	Equipment Upgrade
Requested By:	Brian Thomas (UVA FM CRS)
Outage Coordinator	Donald (Randy) Spencer 434-531-6993
POC for Group Performing Work:	Hudson Payne Electronics Greg Yeatts 434-660-0281 FM Responsible Person: Brian Thomas 434.235.8638
Customers with Whom the Outage was Coordinated:	Bryan Lewis Gene Lawson Wynne Stuart

Outage Approved By:	Randy Spencer (UVA FM Operations)
---------------------	-----------------------------------

Important Notes:

- 1. The specified utility or building system will be out of service as noted above. Please advise the Outage Coordinator immediately if this can not be accommodated in areas under your control or direction
- 2. Those performing work associated with this outage <u>MUST</u> notify the Systems Control Center (982-4685) PRIOR TO THE START and upon COMPLETION of all work

*ALERT*ALERT*ALERT*

Please use the below link to unsubscribe from these notification, change, or subscribe to other building lists

https://www.fm.virginia.edu/resources/outagesubs.html