24078

## \*ALERT\*ALERT\*ALERT\*

**Facilities Management Outage Notification** 

Please Post Centrally in Your Department

## Fire System Fire Suppression, Fire System Panel, Smoke Detection, Sprinkler System Outage

**BLDG: 0058 Rouss Hall** 

Affected Floors / Rooms: Floors 1 & 3

Impact to Building Occupants: No Fire Alarms, No Fire Suppression Replacement of Fire Sprinkler Heads located in Restrooms on the first and third floors.

Please email our team to confirm the outage at: Randy Spencer – DRS2Y@virginia.edu Jacob Campbell – JRC3ZZ@virginia.edu

Scheduled Start Date and Time:	2025-Jun-27 07:00
Scheduled End Date and Time:	2025-Jun-27 16:00
Reason for Outage:	Replace sprinkler heads in restrooms
Requested By:	Brandon Adams
Outage Coordinator	Donald (Randy) Spencer 434-531-6993
Customers with Whom the Outage was Coordinated:	Jay Pence
Outage Approved By:	Randy Spencer (UVA FM Operations)

## **Important Notes:**

- 1. The specified utility or building system will be out of service as noted above. Please advise the Outage Coordinator immediately if this can not be accommodated in areas under your control or direction
- 2. Those performing work associated with this outage <u>MUST</u> notify the Systems Control Center (982-4685) PRIOR TO THE START and upon COMPLETION of all work

Please use the below link to unsubscribe from these notification, change, or subscribe to other building lists

https://www.fm.virginia.edu/resources/outages/outagesubs.html