

3762

ALERT*ALERT*ALERT*ALERT

Facilities Management Outage Notification

Please Post Centrally in Your Department

Fire System - Smoke Detection Outage

BLDG: 0066 MAURY HALL

Affected Floors / Rooms: Attic and 3rd floor smoke detection

Impact to Building Occupants: None

This outage should not affect customers in the building as it will only impact smoke detectors in the 3rd floor and attic.

This Outage Will Occur Daily: 07:30-15:00

Scheduled Start Date and Time:	2019-Aug-07 07:00
Scheduled End Date and Time:	2019-Aug-09 15:30
Reason for Outage:	Smoke Detection outage for structural steel work in the attic of Maury hall
Requested By:	Christopher Bentley (UVA FM Project Services)
Outage Coordinator	Ryan Taylor 434-981-8874
POC for Group Performing Work:	Industrial Fabricators Chad Childress 540-280-5426 FM Responsible Person: P.J. Duprey 434-566-6154
Customers with Whom the Outage was Coordinated:	No customers responded to this outage alert, but it will have no impact to them.
Outage Approved By:	Ryan Taylor

Important Notes:

1. The specified utility or building system will be out of service as noted above. Please advise the Outage Coordinator immediately if this can not be accommodated in areas under your control or direction
2. Those performing work associated with this outage **MUST** notify the Systems Control Center (982-4685) PRIOR TO THE START and upon COMPLETION of all work

ALERT*ALERT*ALERT*ALERT

Please use the below link to unsubscribe from these notification, change, or subscribe to other

building lists

<https://www.fm.virginia.edu/resources/outagesubs.html>