

15677

ALERT*ALERT*ALERT*ALERT

Facilities Management Outage Notification

*Please Post Centrally in Your Department***EMERGENCY****Fire System Smoke Detection Outage****BLDG: 0406 Fayerweather Hall****ALL FLOORS AFFECTED****Impact to Building Occupants: No Fire Alarms****Taking down duct detectors in mechanical room. Removing concrete to repair broken sanitary line**

Scheduled Start Date and Time:	2023-Aug-15 07:30
Scheduled End Date and Time:	2023-Aug-15 15:00
Reason for Outage:	Taking duct detectors offline for concrete removal
Requested By:	Nathan Wilson (UVA FM CC&R)
Outage Coordinator	Donald Spencer 434-531-6993
Customers with Whom the Outage was Coordinated:	Randy Spencer
Outage Approved By:	Randy Spencer (UVA FM Operations)

Important Notes:

1. The specified utility or building system will be out of service as noted above. Please advise the Outage Coordinator immediately if this can not be accommodated in areas under your control or direction
2. Those performing work associated with this outage **MUST** notify the Systems Control Center (982-4685) **PRIOR TO THE START** and upon **COMPLETION** of all work

ALERT*ALERT*ALERT*ALERT**Please use the below link to unsubscribe from these notification, change, or subscribe to other building lists**<https://www.fm.virginia.edu/resources/outagesubs.html>