

**FACILITIES MANAGEMENT** 

### \*ALERT\*ALERT\*ALERT\*ALERT\*

# FIRE ALARM INSPECTION / TEST

#### PLEASE POST CENTRALLY IN YOUR DEPARTMENT

### FACILITIES MANAGEMENT WILL BE INSPECTING / TESTING THE FIRE ALARM SYSTEM IN BLDG:

# 0407 Bayly Bldg

No interruptions in service are expected, *beyond those indicated in this notice.* For unexpected issues related to this test please report to FM Customer Support at 4-1777.

| Additional Information:  |                              |  |
|--------------------------|------------------------------|--|
| FIRE DOORS STATUS:       | Fire Doors Will NOT Close    |  |
|                          |                              |  |
| AHU EQUIPMENT<br>STATUS: | Equipment Will NOT Shut Down |  |
|                          |                              |  |
| ADDITIONAL NOTES:        |                              |  |

| Details Of Testing: |   |  |
|---------------------|---|--|
| Scheduled Dates:    | <b>START:</b> 2024-Aug-12 10:00 <b>END:</b> 2024-Aug-12 11:00 |  |
| Work Order Number:  | 3828398   |  |
| POC For Testing:    | Matthew Brown 434-566-7878                                    |  |
| Approved By:        | Randy Spencer (UVA FM Operations)                             |  |

Additional Notes for Fire System Maintenance Personnel

Note 1: Ensure there is not any troubles on the fire panel when system is back in service

Note 2: Per State Fire Marshal - Fire watch must be provided when the fire alarm or sprinkler systems are out of service.

Note 3: Systems Control (2-4685) prior to starting and upon completion of all work

# \*ALERT\*ALERT\*ALERT\*ALERT\*

Please use the below link to unsubscribe from these notification, change, or subscribe to other building lists https://www.fm.virginia.odu/resources/outagesubs.html

https://www.fm.virginia.edu/resources/outagesubs.html