11263

## \*ALERT\*ALERT\*ALERT\*

**Facilities Management Outage Notification** 

Please Post Centrally in Your Department

## **Fire System Fire Suppression Outage**

BLDG: 5307 SCOTT STADIUM
ALL FLOORS AFFECTED

Impact to Building Occupants: No Fire Suppression Fire Pump being replaced during this outage.

Scheduled Start Date and Time:	2021-Sep-27 06:00 AM
Scheduled End Date and Time:	2021-Sep-30 03:00 PM
Reason for Outage:	Replace Fire Pump and Controller
Requested By:	Forrest Johnson (UVA FM Fire and Life Safety)
Outage Coordinator	Kenny Bower 434-987-4206
Customers with Whom the Outage was Coordinated:	Mike Doto
Outage Approved By:	Kenny Bower (UVA - Facilities Management)

## **Important Notes:**

- 1. The specified utility or building system will be out of service as noted above. Please advise the Outage Coordinator immediately if this can not be accommodated in areas under your control or direction
- 2. Those performing work associated with this outage <u>MUST</u> notify the Systems Control Center (982-4685) PRIOR TO THE START and upon COMPLETION of all work

## \*ALERT\*ALERT\*ALERT\*

Please use the below link to unsubscribe from these notification, change, or subscribe to other building lists

https://www.fm.virginia.edu/resources/outagesubs.html