

FACILITIES MANAGEMENT

*ALERT*ALERT*ALERT*

FIRE ALARM INSPECTION / TEST

PLEASE POST CENTRALLY IN YOUR DEPARTMENT

FACILITIES MANAGEMENT WILL BE INSPECTING / TESTING THE FIRE ALARM SYSTEM IN BLDG:

5307 Scott Stadium

No interruptions in service are expected, *beyond those indicated in this notice*. For unexpected issues related to this test please report to FM Customer Support at 4-1777.

Additional Information:

| Additional information. | | |
|--------------------------|------------------------------|--|
| FIRE DOORS STATUS: | Fire Doors Will NOT Close | |
| AHU EQUIPMENT STATUS: | Equipment Will NOT Shut Down | |
| | | |
| ADDITIONAL NOTES: | | |

Details Of Testing:

| Scheduled Dates: | START: 2024-Jun-06 06:00 AM | END: 2024-Jun-07 12:00 PM |
|--------------------|---|----------------------------------|
| Scrieduled Dates. | This Outage Will Occur Daily | |
| Work Order Number: | 3781874 | |
| POC For Testing: | Matthew Brown 434-566-7878 | |
| Approved By: | Kenny Bower (UVA - Facilities Management) | |

Additional Notes for Fire System Maintenance Personnel

Note 1: Ensure there is not any troubles on the fire panel when system is back in service

Note 2: Per State Fire Marshal - Fire watch must be provided when the fire alarm or sprinkler systems are out of service.

Note 3: Systems Control (2-4685) prior to starting and upon completion of all work

*ALERT*ALERT*ALERT*

Please use the below link to unsubscribe from these notification, change, or subscribe to other building lists

https://www.fm.virginia.edu/resources/outagesubs.html