



FACILITIES MANAGEMENT

ALERT*ALERT*ALERT*ALERT

FIRE ALARM INSPECTION / TEST

PLEASE POST CENTRALLY IN YOUR DEPARTMENT

FACILITIES MANAGEMENT WILL BE INSPECTING / TESTING THE FIRE ALARM SYSTEM IN BLDG:

5507 Palmer Park Softball Stadium

**No interruptions in service are expected, beyond those indicated in this notice.
For unexpected issues related to this test please report to FM Customer Support at 4-1777.**

Additional Information:

FIRE DOORS STATUS:	
AHU EQUIPMENT STATUS:	
ADDITIONAL NOTES:	

Details Of Testing:

Scheduled Dates:	START: 2023-Dec-11 12:00 PM END: 2023-Dec-11 02:00 PM
Work Order Number:	3660636
POC For Testing:	Matthew Brown 434-566-7878
Approved By:	Kenny Bower (UVA - Facilities Management)

Additional Notes for Fire System Maintenance Personnel

Note 1: Ensure there is not any troubles on the fire panel when system is back in service

Note 2: Per State Fire Marshal - Fire watch must be provided when the fire alarm or sprinkler systems are out of service.

Note 3: **Systems Control (2-4685) prior to starting and upon completion of all work**

ALERT*ALERT*ALERT*ALERT

Please use the below link to unsubscribe from these notification, change, or subscribe to other building lists

<https://www.fm.virginia.edu/resources/outagesubs.html>