



ALERT*ALERT*ALERT*ALERT

FIRE ALARM INSPECTION / TEST

PLEASE POST CENTRALLY IN YOUR DEPARTMENT

FACILITIES MANAGEMENT WILL BE INSPECTING / TESTING THE FIRE ALARM SYSTEM IN BLDG:

5507 Palmer Park Softball Stadium

No interruptions in service are expected, beyond those indicated in this notice. For unexpected issues related to this test please report to FM Customer Support at 4-1777.

Additional Information:

FIRE DOORS STATUS:	Fire Doors Will NOT Close
AHU EQUIPMENT STATUS:	Equipment Will NOT Shut Down
ADDITIONAL NOTES:	

Details Of Testing:

Scheduled Dates:	START: 2024-Sep-10 08:30 AM END: 2024-Sep-10 12:00 PM
Work Order Number:	3853079
POC For Testing:	Matthew Brown 434-566-7878
Approved By:	Kenny Bower (UVA - Facilities Management)

Additional Notes for Fire System Maintenance Personnel

Note 1: Ensure there is not any troubles on the fire panel when system is back in service

Note 2: Per State Fire Marshal - Fire watch must be provided when the fire alarm or sprinkler systems are out of service.

Note 3: **Systems Control (2-4685) prior to starting and upon completion of all work**

ALERT*ALERT*ALERT*ALERT

Please use the below link to unsubscribe from these notification, change, or subscribe to other building lists

<https://www.fm.virginia.edu/resources/outagesubs.html>