



UNIVERSITY  
of VIRGINIA

FACILITIES MANAGEMENT

**\*ALERT\*ALERT\*ALERT\*ALERT\***

## **FIRE ALARM INSPECTION / TEST**

*PLEASE POST CENTRALLY IN YOUR DEPARTMENT*

**FACILITIES MANAGEMENT WILL BE INSPECTING /  
TESTING THE FIRE ALARM SYSTEM IN BLDG:**

**5507 Palmer Park**

**No interruptions in service are expected, *beyond those indicated in this notice.***

**For unexpected issues related to this test please report to FM Customer Support at 4-1777.**

### **Additional Information:**

|                                |  |
|--------------------------------|--|
|                                |  |
| <b>AHU EQUIPMENT AFFECTED:</b> |  |
| <b>ADDITIONAL NOTES:</b>       | Air Duct Solution will testing fire dampers. |

### **Details Of Testing:**

|                           |   |
|---------------------------|---|
| <b>Scheduled Dates:</b>   | <b>START:</b> 2025-Jun-18 08:00 <b>END:</b> 2025-Jun-18 14:30 |
| <b>Work Order Number:</b> | jes5k@virginia.edu  |
| <b>POC For Testing:</b>   | James Spears 434-531-6970                                     |
| <b>Approved By:</b>       | James Spears (UVA FM Fire and Life Safety)                    |

### **Additional Notes for Fire System Maintenance Personnel**

**Note 1: Ensure there is not any troubles on the fire panel when system is back in service**

**Note 2: Per State Fire Marshal - Fire watch must be provided when the fire alarm or sprinkler systems are out of service.**

**Note 3: Systems Control (2-4685) prior to starting and upon completion of all work**

**\*ALERT\*ALERT\*ALERT\*ALERT\***

**Please use the below link to unsubscribe from these notification, change, or  
subscribe to other building lists**

**<https://www.fm.virginia.edu/resources/outagesubs.html>**